



STATE OF WASHINGTON
DEPARTMENT OF ECOLOGY

1315 W. 4th Avenue • Kennewick, Washington 99336-6018 • (509) 735-7581

October 11, 1996

Mr. James E. Rasmussen
U.S. Department of Energy
P.O. Box 550, MS: A5-15
Richland, WA 99352

Mr. William D. Adair
Fluor Daniel Hanford, Inc.
750 George Washington Way, Ste. 1
Richland, WA 99352

OUT 1996
FIVE
M

Dear Messers. Rasmussen and Adair:


Re: Hanford Facility Permit Part A, Forms 1 and 3 for Treatment, Storage, and/or Disposal Units
Assigned to Fluor Daniel Hanford, Inc. and Discrepancies for 4843 Alkali Metal Storage
Facility

The Washington State Department of Ecology (Ecology) acknowledges receipt of the revised Part A, Forms 1 and 3 for thirty-three units assigned to Fluor Daniel Hanford, Inc. as co-operator.

During review of the Part A, Form 1 for the 4843 Alkali Metal Storage Facility (AMSF), Ecology has identified a discrepancy. The D002 waste code for corrosivity was omitted. Please correct this error on the front page of the final version of the Part A, Form 1, which will be submitted to Ecology stamped "CLOSED" upon completion of closure of this unit. Any other comments on the subject forms will be submitted in future correspondence.

If you have any questions regarding the 4843 AMSF, please contact Greta P. Davis at (509) 736-3025. Please refer any other questions to me at (509) 736-3016.

Sincerely,


Moses Jaraysi
Nuclear Waste Program

GPD:MJ:sb

cc: Dave Bartus, EPA
Cliff Clark, USDOE
Sue Price, FDH
J.R. Wilkinson, CTUIR
Donna Powaukee, NPT

Russell Jim, YIN
Mary Lou Blazek, ODOE
Administrative Record

